



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 12, 2013

Reviewed: 

Mine Name: Saturday Night Mine	Permit Number: S/003/0076
Operator Name: Perihelion Global, Inc	Inspection Date: June 4, 2013
Inspector(s): Lynn Kunzler, Steve Schneider, DOGM	Time: 10:15 am
Other Participants: None	Mine Status: Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine Inspection.

Inspection Summary:


This site was reclaimed during November of 2012, using forfeited funds from the reclamation surety. Reclamation included backfilling the adits, regrading the waste dumps, pads and access road. The road was left in a roughened condition to encourage water catchment and vegetation establishment, and discourage vehicle use. There has been no apparent attempt to access the site with wheeled vehicles.

The area was stable, with no apparent erosion or settling/subsidence at the adit areas. Vegetation was emerging, but was too immature to identify several of the species, however there were several different grass, forb and shrubs observed – including some that were not in the seed mix.

Photos were taken to document site conditions

Conclusions and Recommendations:

At this time, reclamation efforts appear to be successful and vegetation is establishing. This will need to be checked again in a year or two.

Inspector's Signature 

cc: Mike Nelson, BLM (mnelson@blm.gov)

O:\M003-BoxElder\S0030076-SaturdayNight1and2\inspections\Insp-06042013.doc